



INSPECTION LOCATION: 1950 MONTREAL RD CORNWALL K6H 1G2 INSPECTION CUSTOMER: NAV CANADA 1950 MONTREAL RD CORNWALL K6H 1G2	INSPECTION DETAILS Date of Inspection: Sep 08, 2021 Total Hours: 6.25 (Travel time not included) Type: Inspection of a Major Alteration (Elevating Devices) Reference No.: 39782 Equipment: Passenger Elevator Building Type: HOTEL
Inspection report delivered by email: NAV CANADA(info@rideauelevator.ca) RIDEAU ELEVATOR SERVICES INC	

INSPECTION NOTES
Inspection order(s) are issued pursuant to my authority under section 21. (1) of the Technical Standard and Safety Act, 2000.
TSSA has completed an inspection of the major alteration. This device may be put into service.

RESOLVED/REVOKED INSPECTION ORDERS			
No.	Inspection Order(s)	Issued Date	Status
1	ASME A17.1/CSA B44-10 2.26.2 When a stop switch is activated (operated, opened), it shall cause the electric power to be removed from the elevator driving machine motor and brake. top of car stop switch not working	Sep 08, 2021	Resolved

This report is issued under the *Technical Standards and Safety Authority Act, 2000, s. 17 (1)*

17. (1) An inspector may conduct an inspection and may, as part of that inspection, enter and inspect at any reasonable time the lands and premises where any of the things, parts of things or classes of things to which this Act, the regulations or a Minister's order apply are used, operated, installed, made, manufactured, repaired, renovated or offered for sale for the purpose of,
(a) ensuring compliance with this Act, the regulations or a Minister's order;
(b) ensuring that an authorization holder remains entitled to the authorization; or
(c) determining whether a hazardous condition exists. 2006, c. 34, s. 25 (5).

As a not-for-profit regulatory authority, TSSA operates on a cost recovery basis.