



INSPECTION LOCATION: 1950 MONTREAL RD CORNWALL K6H 1G2 INSPECTION CUSTOMER: NAV CANADA 1950 MONTREAL RD CORNWALL K6H 1G2	INSPECTION DETAILS Date of Inspection: Jan 12, 2021 Total Hours: 5.5 (Travel time not included) Type: Inspection of a Major Alteration (Elevating Devices) Reference No.: 30782 Equipment: Passenger Elevator Building Type: ASSEMBLIES
Inspection report delivered by email: NAV CANADA(info@rideauelevator.ca) (rsampson@rideauelevator.ca) RIDEAU ELEVATOR SERVICES INC	

INSPECTION NOTES

Inspection order(s) are issued pursuant to my authority under section 21. (1) of the Technical Standard and Safety Act, 2000.

TSSA has completed an inspection of the major alteration. This device may be put into service. Failure to comply with inspection orders by the required date may result in this device being removed from service.

ISSUED INSPECTION ORDER(S) TO: NAV CANADA

No.	Inspection Order(s)	Issued Date	Compliance Date
1	ASME A17.1/CSA B44-10 2.27.1.1 The two-way communication means shall provide on demand to authorized personnel, information that identifies the building location and elevator number and that assistance is required.	Jan 12, 2021	Apr 12, 2021
2	ASME A17.1/CSA B44-10 2.27.1.1 The two way communication means in the car shall be equipped with means that automatically verifies the operability of the telephone line (or other method used such as VOIP etc.) at least once daily.	Jan 12, 2021	Apr 12, 2021
3	ASME A17.1/CSA B44-10 2.13.4.2 Provide/Maintain the door operator data plate / data tag with related door closing times.	Jan 12, 2021	Apr 12, 2021
4	ASME A17.1/CSA B44-10 2.27.2 Emergency power operation shall be tested by simulation or actual operation.	Jan 12, 2021	Apr 12, 2021
5	ASME A17.1/CSA B44-10 2.27.3.2 The automatic emergency recall operation shall be tested before the last car in the building is licensed.	Jan 12, 2021	Apr 12, 2021
6	OESC 2015 30-314 Provide a guard to protect overhead lighting less than 2.1 meters above machine room floor.	Jan 12, 2021	Apr 12, 2021
7	ASME A17.1/CSA B44-10 2.10.1 Provide guarding in the machine room / machine space to protect against accidental contact.	Jan 12, 2021	Apr 12, 2021

This report is issued under the *Technical Standards and Safety Authority Act, 2000, s. 17 (1)*

17. (1) An inspector may conduct an inspection and may, as part of that inspection, enter and inspect at any reasonable time the lands and premises where any of the things, parts of things or classes of things to which this Act, the regulations or a Minister's order apply are used, operated, installed, made, manufactured, repaired, renovated or offered for sale for the purpose of,
(a) ensuring compliance with this Act, the regulations or a Minister's order;
(b) ensuring that an authorization holder remains entitled to the authorization; or
(c) determining whether a hazardous condition exists. 2006, c. 34, s. 25 (5).

As a not-for-profit regulatory authority, TSSA operates on a cost recovery basis.



Report No.: 8825221
Report Date: Jan 12, 2021

Inspector: Le Breton, Jason
Phone: 613-809-4196
Email: jlebreton@tssa.org

ISSUED INSPECTION ORDER(S) TO: NAV CANADA			
No.	Inspection Order(s)	Issued Date	Compliance Date
	.		

This report is issued under the *Technical Standards and Safety Authority Act, 2000, s. 17 (1)*

17. (1) An inspector may conduct an inspection and may, as part of that inspection, enter and inspect at any reasonable time the lands and premises where any of the things, parts of things or classes of things to which this Act, the regulations or a Minister's order apply are used, operated, installed, made, manufactured, repaired, renovated or offered for sale for the purpose of,
(a) ensuring compliance with this Act, the regulations or a Minister's order;
(b) ensuring that an authorization holder remains entitled to the authorization; or
(c) determining whether a hazardous condition exists. 2006, c. 34, s. 25 (5).

As a not-for-profit regulatory authority, TSSA operates on a cost recovery basis.