

TECHNICAL STANDARDS and SAFETY AUTHORITY

345 Carlingview Drive Toronto, Ontario M9W 6N9 Toll free 1-877-682-8772 www.tssa.org

Inspection Report

Report No.: 8853735 Report Date: May 13, 2021

Inspector: Le Breton, Jason Phone: 613-809-4196 Email: jlebreton@tssa.org

INSPECTION LOCATION:

1950 MONTREAL RD

CORNWALL K6H 1G2

INSPECTION CUSTOMER: NAV CANADA

1950 MONTREAL RD CORNWALL K6H 1G2 INSPECTION DETAILS

Date of Inspection: May 12, 2021

Total Hours: .75 (Travel time not included)

Type: Subsequent Inspection (Elevating Devices)

Reference No.: 30782

Equipment: Passenger Elevator
Building Type: ASSEMBLIES

Inspection report delivered by email: NAV CANADA(info@rideauelevator.ca)

RIDEAU ELEVATOR SERVICES INC RIDEAU ELEVATOR SERVICES INC

INSPECTION NOTES

Inspection order(s) are issued pursuant to my authority under section 21. (1) of the Technical Standard and Safety Act, 2000.

TSSA has completed an inspection of this device. All outstanding orders have been resolved.

No.	Inspection Order(s)	Issued Date	Status
1	ASME A17.1/CSA B44-10 2.27.1.1	Jan 12, 2021	Resolved
	The two-way communication means shall provide on demand to authorized personnel, information that identifies the building location and elevator number and that assistance is required.		
2	ASME A17.1/CSA B44-10 2.27.1.1	Jan 12, 2021	Resolved
	The two way communication means in the car shall be equipped with means that automatically verifies the operability of the telephone line (or other method used such as VOIP etc.) at least once daily.		
3	ASME A17.1/CSA B44-10 2.13.4.2	Jan 12, 2021	Resolved
	Provide/Maintain the door operator data plate / data tag with related door closing times.		
4	ASME A17.1/CSA B44-10 2.27.2	Jan 12, 2021	Resolved
	Emergency power operation shall be tested by simulation or actual operation.		
5	ASME A17.1/CSA B44-10 2.27.3.2	Jan 12, 2021	Resolved
	The automatic emergency recall operation shall be tested before the last car in the building is licensed.		
6	OESC 2015 30-314	Jan 12, 2021	Resolved
	Provide a guard to protect overhead lighting less than 2.1 meters above machine room floor.		
7	ASME A17.1/CSA B44-10 2.10.1	Jan 12, 2021	Resolved
	Provide guarding in the machine room / machine space to protect against accidental contact		

This report is issued under the Technical Standards and Safety Authority Act, 2000, s. 17 (1)

17. (1) An inspector may conduct an inspection and may, as part of that inspection, enter and inspect at any reasonable time the lands and premises where any of the things, parts of things or classes of things to which this Act, the regulations or a Minister's order apply are used, operated, installed, made, manufactured, repaired, renovated or offered for sale for the purpose of,

(a) ensuring compliance with this Act, the regulations or a Minister's order; (b) ensuring that an authorization holder remains entitled to the authorization; or

(c) determining whether a hazardous condition exists. 2006, c. 34, s. 25 (5).