

TECHNICAL STANDARDS and SAFETY AUTHORITY

345 Carlingview Drive Toronto, Ontario M9W 6N9 Toll free 1-877-682-8772 www.tssa.org

Inspection Report

Report No.: 8885940 Report Date: Apr 16, 2021

Inspector: Le Breton, Jason Phone: 613-809-4196 Email: jlebreton@tssa.org

INSPECTION LOCATION:

1950 MONTREAL RD CORNWALL

K6H 1G2

INSPECTION CUSTOMER: NAV CANADA

NAV CANADA 1950 MONTREAL RD CORNWALL K6H 1G2 INSPECTION DETAILS

Date of Inspection: Apr 15, 2021

Total Hours: **5.5** (Travel time not included)

Type: Inspection of a Major Alteration (Elevating Devices)

Reference No.: 30816

Equipment: Passenger Elevator
Building Type: ASSEMBLIES

Inspection report delivered by email: NAV CANADA(info@rideauelevator.ca)

RIDEAU ELEVATOR SERVICES INC RIDEAU ELEVATOR SERVICES INC

INSPECTION NOTES

Inspection order(s) are issued pursuant to my authority under section 21. (1) of the Technical Standard and Safety Act, 2000.

TSSA has completed an inspection of the major alteration. This device may be put into service.

This report is issued under the Technical Standards and Safety Authority Act, 2000, s. 17 (1)

17. (1) An inspector may conduct an inspection and may, as part of that inspection, enter and inspect at any reasonable time the lands and premises where any of the things, parts of things or classes of things to which this Act, the regulations or a Minister's Min

(a) ensuring compliance with this Act, the regulations or a Minister's order; (b) ensuring that an authorization holder remains entitled to the authorization; or

(c) determining whether a hazardous condition exists. 2006, c. 34, s. 25 (5).